

Amerex Corporation

P.O. Box 81
Trussville, AL 35173-0081
205.655.3271 p
800.654.5980 f
<http://www.amerex-fire.com>



Subject: Gyro Cooker Coverage

Date: February 20, 2017

File: 0004.1.A_ Gyro Cooker

Amerex recommends the use of our single flow nozzle, P/N 11982, for gyro cookers. The nozzle is to be located directly above the appliance, aiming straight down toward the center of the drip pan. One (1) nozzle will cover an area 36" long x 30" wide. The nozzle should be located at a height of 36" to 40" above the drip pan.

If the nozzles are not cleaned and/or replaced every six months, because of the heat and grease, the nozzle may fail to extinguish the possible fire. It is imperative proper maintenance be performed to insure proper function of the system. There is no specific Underwriters Laboratories test for a gyro cooker. However, the above recommendation is based on sound fire protection backed by our extensive knowledge of fire testing and kitchen protection.

If you have any further questions please feel free to contact me at (205)655-3271.

Sincerely,
Derek J. Bryant
Amerex Corporation
Applications Engineer/KP & IS
E-mail: derek.bryant@amerex-fire.com
· tech.services@amerex-fire.com